

### The Bangkok Earthquake and What we learned from it

### Pennung Warnitchai

Professor of Structural Engineering Asian Institute of Technology (AIT)

Director of Earthquake Research Center of Thailand (EARTH)





SHAKING	Not felt	Weak	Light	Moderate	Strong	Very strong	5evere	Violent.	Extreme
DAMAGE	None	None	None	Very light	Light	Moderate	Moderate/heavy	Heavy	Very heavy
PGA(%g)	<0.0464	0.297	2.76	6.2	11.5	21.5	40.1	74.7	>139
PGV(cm/s)	+0.0215	0.135	1.41	4.65	9.64	20	41.4	85.8	>178
INTENSITY	10	11-111	IV	v	VI	VII	VIII	100	<b>36</b> 0

A Seismic Instrument o Reported Intensity


Epicenter Rupture

# M 7.7 - 2025 Mandalay, Burma (Myanmar) Earthquake

### 2025-03-28 06:20:54 (UTC) 22.013°N 95.922°E 10.0 km depth







Map showing Soil (Site) Conditions in Thailand (derived from digital elevation data—SRTM30 and boreholes data)

Bangkok and neighboring provinces are located inside a large soil basin.


**Rock** (No Amplification)

Very Stiff Soil


Stiff Soil (Moderate Amplification)

Moderately Soft Soil


Very Soft Soil (High Amplification)



### **Resonance Effect**



### Depth to Basement Rock in Bangkok Basin



# Bangkok and the surrounding provinces are at risk of disasters from distant large earthquakes

The city lies on a large and deep soil basin, which can strongly amplify long-period ground motions. A large number of high-rise buildings with long natural periods will be strongly shaken by the resonance with these amplified ground motions


Earthquake scenarios that are dangerous for tall buildings in Bangkok include:

Earthquake of magnitude 7-7.5 in Kanchanaburi province Earthquake of magnitude 8 along the Sagaing Fault in Myanmar Earthquake of magnitude 8.5-9 at the Arakan subduction zone

หน้า ๑๗ เล่ม ๑๒๙ คอนที่ ๗๖ ก ราชกิจจานุเบกษา ๓๐ พฤศจิกาอน ๒๕๕๐	เสม ๑๒๙ ดอนที่ ๙๖ ก	หน้า ๑๐/ วาชกิจจานุเบกษา	๓๐ พฤศจิกาชน ๒๙๕๐
With the 2007 amendment to the Earthqu the control area for earthquake-resistant and the surrounding provinces. กฎกระทรวง กับนุกาวรับน้ำหนัก ความค้านทาน ความคงทนงองอากาว	เองการอาการเรา อำารองแทร องการออก อำารองการเรา อำารองแทร องการออก ออก อาการจะคร (๑) บริเวณต้าระร้องและบ (๓) อาการที่จำเป็นต่ ด้างอิน ออกนิทันเพลิง อาการจูนย์ โรงพอิทและเก็บน้ำประปา	inisterial การเกิด Addition (Additional) Addition (Additional) (Addit	Bangkok เช่น สอานพยาบาลที่วับผู้ป่วยไว้
และพื้นสินที่รองรับอาคารในการด้านทานแรงสั่นสะเทือนของแผ่นคินไหว ท.ส. ๒๕๕๐ อาสัยอ่านาจตามความในมาตรา ๕ (๓) แห่งพระราชบัญญัคีควบคุมอาคาร ท.ส. ๒๕๒๒ และมาตรา ๘ (๑) แห่งพระราชบัญญัติควบคุมอาการ ท.ศ. ๒๕๒๒ ซึ่งแก้ไขเพิ่มเดิมโดย พระราชบัญญัติควบคุมอาคาร (ฉบับที่ ๑) พ.ศ. ๒๕๔๓ อันเป็นกฎหมายที่มีบทบัญญัติบางประการ เกี่ย <del>าว์ เคาร์ เว็บวิจา วิจานาร เรี</del> ่นนาร ราชป	หรือวัตถุที่วะเบิดได้ (ค) อาดารสารารณ หอประชุม หอดิลป์ พิพิธภัณฑ ห้างสรรพสินค้า ศูนย์การด้า สถานีร (ง) สถานศึกษาที่รับ (ง) สถานรับเลี้ยงเดี้	ะที่มีผู้ใช้อาคารได้ตั้งแต่สามริ สถาน หอสมูด กาสนสถา	้อยคนขึ้นไป ได้แก่ โรงมพรสพ ม สนามกีฬา อัฒจันทร์ คลาค กองร้อยท้าสิบคนขึ้นไป
"บริเวณที่ ๑"หมายความว่า พื้นที่หรือบริเ จากแผ่นดินไหวระยะไกล ได้แก่ กรุงเทพมหานคร สมุทรปราการ และจังหวัดสมุทรสาคร	จังหวัดนนทบุรี จังเ	หวัดปทุมธานี จํ	สบเมตรงนาบ โงหวัด <sup>รัวฝ่ายปีความสูง</sup> ยาลที่รับผู้ป่วยไว้
"บริเวณเฟ้าระวัง" หมายความว่า พื้นที่หรือบริเวณที่อาจได้รับผลกระทบอากแผ่นดีนไหว ได้แก่ อังหวัดกระบี่ จังหวัดชุมพร อังหวัดทั่งงา จังหวัดภูเก็ด อังหวัดระนอง จังหวัดสงขอา และ จังหวัดสู่รามฏร์ธานี "บริเวณที่ ๑" หมายความว่า พื้นที่หรือบริเวณที่เป็นดินอ่อนมากที่อาอได้รับผลกระทบ จากแผ่นดินใหวระอะไกล ได้แก่ กรุงเทพมหานลร จังหวัดนนทบุรี จังหวัดปทุมธานี จังหวัด สบุทรปราการ และจังหวัดสบุทรสาดร	โรงผลิตและเก็บน้ำประปา (พ) อาคารเก็บวัคถูย่ หรือวัคฉุที่ระเบิดได้	วันคราย เช่น วัตถุระเบิด วัตถุ มะ ใต้แก่ โรงมหรสท ทอป	ขสอสาร มายากโคยาน โรงไฟฟ้า ใวไฟ วัดอุมิพิษ วัดอุดัมบันตรังสี วะขุม หอศิลป์ พิพิธภัณฑเสอาน ล้า ศูนย์การก้า สถานีรถ โรงแรม

### NAM'1301/1305-01

มาตรฐานการออกแบบอาดารต้านทาน การสั่นสะเทือนของแพ่นดินไหว





กรมโยธาธิการและพังเมือง กระทรวงมหาดไทย W.G. 2561


**National Standard DPT** 1301/1302-61: **Seismic Resistant Design of Buildings and Structures** 


*Issued by Department of Public* Works and Town & Country Planning, Ministry of Interior (2019)


The new design spectra for Bangkok and the surrounding provinces have already been included in DPT1301/1302-61.











# **Overall Building's Condition** (Government building, Bangkok Metropolitan Area)

Total Government building = **498** 

**454** buildings (91.2%)

**42** buildings (8.4%)

**2** buildings (0.4%) –



Shear wall, elevator shaft, and fire escape stairs on the 3rd and 4th floors were damaged.



Serious damage on columns from 5<sup>th</sup> to 27<sup>th</sup> floor, along with cracks in the walls.



# Summary of Damages

Total Collapse – 1 Bldg (SAO bldg. during construction)

Structural damages – Approx. more than 10 Bldgs


Non-structural damages – Approx. Several 100 Bldgs

All buildings in Bangkok, except collapsed SAO bldg, are safe from the earthquake with varying of damages but no reported injuries or death, except the collapsed SAO bldg with around 100 labors death or missing.

# Door Corner Cracking in Masonry Wall (commonly seen 15/15)




# Spalling of interior and exterior plaster (commonly seen 14/15)




### Severe cracking of masonry wall on both side (rarely seen, 2/15)




# Significant Structural Damage (25-story, Rajavithi Hospital)



### Significant Structural Damage (25-story, Rajavithi Hospital)



### Significant Structural Damage (25-story, Rajavithi Hospital)



# Significant Structural Damage (Building in Bangkok)




#### Damage and Implications for Seismic Design of RC Structural Wall Buildings

John W. Wallace,<sup>a)</sup> MEERI, Leonardo M. Massone,<sup>b)</sup> Patricio Bonelli,<sup>c)</sup> Jeff Dragovich,<sup>d)</sup> MEERI, René Lagos,<sup>e)</sup> Carl Lüders,<sup>f)</sup> and Jack Moehle,<sup>g)</sup> MEERI

Earthquake Spectra, Volume 28, No. S1, pages S281-S299, June 2012




Figure 1. Typical wall damage in the 2010 Chile earthquake.




#### Station: Department of Public Works and Town & Country Planning (PWSA)

PWSA - NE


PWSA - NN



### **Damped Free Vibration**



### **Harmonic Shaking**



2.5%

1.0%

36

.40

14

10

36


101

16

#### Station: Department of Public Works and Town & Country Planning (PWSA)


PWSA - NE

**PWSA - NN** 



BKSI - NE


BKSI - NN



#### Station: King Mongkut's University of Technology Thonburi (KMUA)

KMUA - NE

**KMUA - NN** 






### Building model


	Linear Static		Modal	
Model	Base Reaction	Base Reaction Period (s)		
woder	(Ton)	Mode 1	Mode 2	Mode 3
Linear-elastic		2.883	2.272	2.050
Linear-elastic	53725.51	UX	UY	RZ












Mode 1 X

Mode 2 Y

Mode 3 Z



SHAKING	Not felt	Weak	Light	Moderate	Strong	Very strong	5evere	Violent.	Extreme
DAMAGE	None	None	None	Very light	Light	Moderate	Moderate/heavy	Heavy	Very heavy
PGA(%g)	<0.0464	0.297	2.76	6.2	11.5	21.5	40.1	74.7	>139
PGV(cm/s)	+0.0215	0.135	1.41	4.65	9.64	20	41.4	85.8	>178
INTENSITY	10	11-111	IV	v	VI	VII	VIII	100	<b>36</b> 0

A Seismic Instrument o Reported Intensity

Epicenter Rupture

# M 7.7 - 2025 Mandalay, Burma (Myanmar) Earthquake

### 2025-03-28 06:20:54 (UTC) 22.013°N 95.922°E 10.0 km depth





Figure 22. Map and chart of potential maximum earthquake magnitudes (*M*<sub>w</sub>) associated with named segments of the Sagaing fault. Blue arrows show the boundaries of fault segments. Ruptures of the past century appear in the lower box. Green lines are the proposed rupture patches along the Sagaing fault since the beginning of the twentieth century; gray line shows the proposed rupture section along the Kyaukkyan fault, parallel to the Sagaing fault. Red line marks the possible rupture patch of the 1839 earthquake, inferred from historical data. BMs = Ban Mauk segment; TMs = Tawma segment; IDs = In Daw segment; MIs = Mawlu segment; SZs = Shaduzup segment; KMs = Kamaing segment; MCs = Mogang segment.

#### Station: Department of Public Works and Town & Country Planning (PWSA)


PWSA - NE


PWSA - NN



A basic requirement for walls to be ductile: **a flexural plastic hinge zone should be formed at the base of the wall**, **and brittle failure mechanisms should not be permitted to occur**.


This is achieved by establishing a desirable hierarchy in the failure mechanics using **capacity design procedures** and by appropriate detailing of the potential plastic hinge region.





*Failure modes* to be prevented are:

- Diagonal tension failure (c) caused by shear,
- Diagonal compression failure caused by shear,
- Instability of thin walled sections,
- Instability of the principal compression reinforcement,
- Sliding shear along construction joints (d),
- Shear or bond failure along lapped splices or anchorages (b).




The Cyclic Behavior of A 44-Story Building with Ductile Structural Walls


#### Station: Department of Public Works and Town & Country Planning (PWSA)


PWSA - NE

PWSA - NN



### Fluid Viscous Damper (FVD) for building vibration control





https://www.linkedin.com/posts/ncsea\_fluid-viscous-dampers-effectively-dissipateactivity-7146470330536968192-SYJS/



https://ana.ir/en/news/1973/iran-among-nine-countries-holding-viscous-fluid-damper-technology



https://doi.org/10.3390/buildings15020260



https://ryanrakhmats.wordpress.com/2018/04/22/fluid-viscous-damper-fvd/